

# LMS2, Service Bulletin, LASX065 Harness Update

#### **Description of Service Bulletin**

This SB relates to a change in the system harness (P/N: LMS2-LASX065). The revision 2 harnesses have updated connectors which provide greater reliability (mating force and environmental) as well as improved manufacture speed and yield.

### **Affected Components**

• LMS2-LASX065 – System Harness

#### **Compliance Requirements**

**Information Only** 

## **Action Required**

All installers should be aware of the changes to the connectors.

 The Forward/Reverse harness still contains blue and green wires; however it is fitted with a 3 pin male connector with female terminals. Position 3 is for the stabiliser (when fitted). It mates with a 3 pin female connector with male terminals in the system harness.



• The control panel harness is a 4 pin female connector with male terminals. The harness is still fitted with orange, purple and yellow wires. It mates with a 4 pin male connector on the system harness.



The camera power connector is fitted with a 2 pin connector.

#### **Additional Notes**

Please visit <a href="http://sil3.com.au/lms2/">http://sil3.com.au/lms2/</a> for further information.